



Celebrate
PUBLIC WORKS!



APWA WA



APRIL 10-11, VANCOUVER WA
2024 SPRING CONFERENCE

Structural Rehabilitation Under Severe Access Constraints



Brendan O'Sullivan, PE | Consor

Jerry Barnett, PE | Clark Regional Wastewater District



consor



LEARNING OBJECTIVES

Objective 1 -

Identify, evaluate, and select rehabilitation technologies to meet project goals

Objective 2 -

Develop an approach to mitigate project risks

Objective 3 -

Utilize the latest technological advances to ensure project success



Agenda

- Background
- Overview
- Project Goals
- Timeline
- Condition Assessment
- Design
- Permitting Strategy
- Construction
- Project Takeaways




Background

- Owner: Clark Regional Wastewater District
- Location: Vancouver, WA
 - Cougar Canyon
- Trunk Characteristics:
 - 10,078 Linear-feet
 - 12- to 15-inch diameter RCP
 - Constructed 1978-79



Background



Background

Planned Corridor Projects

1. Hazard Mitigation / Exposed Pipe
2. Structural Rehab of Trunk
3. Stream Resiliency and banks stability – Future/Pending



Project Overview

Rehabilitation of:

- 4,078 Linear-feet
- 15-inch diameter RCP
- 19 Manholes
 - Interior coating
 - Lids, steps, & concrete




Project Goals

1. Structural Rehab
2. Corrosion Protection
3. Maximize Capacity
4. Construct in 2022



Timeline






Celebrate
PUBLIC WORKS!
APWA WA 🎉🔥👏

Preliminary Design

Condition Assessment

- Phase 1: CCTV Inspection
- Phase 2: Supplemental CCTV




Condition Assessment

- Phase 1:
 - CCTV Inspection
 - Visual Inspection of exposed pipe




Condition Assessment

- Phase 2:
 - Supplemental CCTV Inspection
 - Verification
 - Recommendations



Condition Assessment - Results

- PACP Grades 4 and 5
- Wall loose ½" to 1"
- Exposed reinforcement
- Cracking



Bypass Flows

- Flow Monitoring

Range = 175 to 1,200 gpm

Average = 572 gpm





Celebrate
PUBLIC WORKS!
APWA WA 🎉🔥👏

Design Phase


Design Challenges

- Access Constraints
- Staging Limitations
- Environmental Corridor
- Permitting Timeline



Access & Staging

- LEGEND**
- COUNTY OWNED TAX LOT
 - PERMIT OF ENTRY AREA
 - POTENTIAL STAGING AREA
 - PUBLIC RIGHT-OF-WAY ACCESS
 - TEMPORARY CONSTRUCTION EASEMENT AREA
 - ACCESS ROUTE
 - MANHOLE



Permitting

Existing Conditions:


- Creek Corridor
- Environmental Sensitive Area
- Delineated Wetlands

Strategy:

- Avoid permit triggers

Approach:


- Minimize disturbed area
- Use technology suited to strategy



Permitting

Triggers to avoid:

- No vehicles
- No tree felling
- Minor limbing only
- No excavation
- No fill



Design – Alternatives Analysis


Criteria:

- Fully structural rehab
- Feasibility / Constructability
- Contractor availability & experience
- Capacity Retention
- Cost



Design – Alternatives Analysis

- Technologies
 - Sliplining
 - Spiral Wound Pipe
 - Cured-In-Place Pipe (CIPP)
 - Thermal Cure
 - UV Cure



Design – Alternatives Analysis

	<i>Sliplining</i>	<i>Spiral Wound Pipe</i>	<i>Thermal CIPP</i>	<i>UV CIPP</i>
Fully Structural Rehab	Green	Green	Green	Green
Constructability	Red	Green	Red	Green
Contractor Availability	Green	Red	Green	Green
Capacity Retention	Red	Yellow	Green	Green
Cost	Yellow	Yellow	Green	Green



Design – CIPP Liner

Characteristics	Parameter
Initial Flex Strength	6,500 psi
Initial Flex Modulus	1,245,000 psi
Condition	Fully Deteriorated
Design Life	> 50 years
Factor of Safety	2





Celebrate
PUBLIC WORKS!
APWA WA 🎉🔥👏

Bidding & Construction


Bid Results

	Bid Amount
Bidder #1	\$1,960,208.04
EOPCC	\$1,973,042.60
Bidder #2	\$2,145,373.16
Bidder #3	\$2,168,000.00
Bidder Average	\$2,156,686.58




Construction Challenges

- **Access**
 - Steep slopes
 - Narrow paths
- **Bypass Pumping**
- **Wet Weather Potential**



Access Challenges



Bypass Systems

- Two Systems
 - Main
 - Lateral
- Two Set-ups



Bypass Systems – Main & Lateral

Mainline System:

- 6" HDPE piping
- Two 6" Dri-Prime pumps
- Floats & auto-dialers

Lateral System:

- 4" HDPE piping
- 3" trash pumps



Bypass System - Flows

- Expected = 210 gpm
- Actual = 574 gpm



UV CIPP


- Thicknesses
 - 3.0 and 3.8 mm
- Test Results
 - Flex Mod = 2,310,000 psi
 - Flex Strength = 64,900 psi



UV CIPP




UV CIPP



Manhole Rehabilitation

Two categories:

1. Rehabilitation
2. Improvements



Manhole Rehabilitation

Rehabilitation:


- Silicate mortar concrete rehab
- Epoxy coating



Manhole Rehabilitation

Improvements:

- Composite locking lid
- Polypropylene steps





Manholes – Before & After



Project Takeaways

- Communication
 - Internal Team / Contractor
 - Public / Residences
- Match strategies to technology
- Match technology to conditions
- Risks mitigation




Special Thanks!

- **CRWWD:**
 - Jose Gonzalez
 - John Parela
 - Tom Grange
- **Contractors:**
 - Iron Horse, LLC
 - Olsen Brothers Pro-vac, LLC



Celebrate
PUBLIC WORKS!
APWA WA 🎉🔥👏



Please take a few minutes to use the evaluation form on the mobile app and provide your feedback on this session!

Evaluations help us select sessions for future conferences and provide valuable feedback for conference planners & speakers.

Thank you!



Thank You

Questions?

Brendan O'Sullivan, P.E., Consor
Email: Brendan.OSullivan@consoreng.com

Jerry Barnett, P.E., Clark Regional Wastewater District
Email: jbarnett@crwwd.com